

Notice

TO ALL OWNERS & RESIDENTS:

Ref No. 17-65

VEHICLE TRANSPONDER SYSTEM

In order to improve the performance of our Vehicle Transponder system, we have:

- 1) Repositioned the *Entrance & Exit Transponder Readers*
- 2) Installed *Optical Beam Sensors ('Arming Loops')*

Residents using Vehicle Transponders are reminded to

- (a) Drive **SLOWLY** when approaching the Transponder Readers
- (b) Maintain a distance of at least 3ft from the Car ahead of you when approaching the Barrier gate.

Please immediately inform the Management Office, should you experience any difficulty with your Transponder.

Thank you.


The Management
Date: 10 November 2017

PERBADANAN PENGURUSAN KIARAMAS CENDANA

(PTG/WP.20/1/2330)

10-G-03, Kiaramas Cendana Condominium, 10 Jalan Desa Kiara, Bukit Kiara, 50480 Kuala Lumpur.

Tel: 03-6203 7768 Fax: 03-6203 7769 Email: k.cendana@gmail.com



Kiaramas
Cendana